

# Stepper Motor Driver CW8060

## 1. Introduction

### Descriptions

The CW8060 driver is a cost-effective and high performance stepping driver. The design is based on an advanced control technology. It applies to two-phase or four-phase hybrid stepping motor below 6A, such as 85BYG, 57BYG. Due to the adoption of the advanced bipolar constant-current chopper driver technology. It shows many features such as stable operation and excellent high speed torque. It has 14 kinds of micro-step, and the maximum number of micro-step is 1/256 (step number is 51200 steps/rev); its current range is 2A-6A, the output current has 8 settings, and the current resolution is about 0.5A; it has many functions such as automatic semi-flow, over-voltage, under-voltage and over-current protection. The driver is the DC power supply, the operating voltage range should be 36VDC-80VDC, and it should not exceed 90VDC and not less than 24VDC.

### Applications

It is suitable for a variety of large-scale automation equipments and instruments, such as labeling machine, cutting machine, packaging machine, plotter, engraving machine, CNC machine tools and so on.

### Features

- High-performance, low price
- micro-step
- Automatic idle-current reduction
- Optical isolating signal I/O
- Max response frequency up to 75Kpps
- Low temperature rise, smooth motion
- Online adaptive PID technology

### application

It is suitable for a variety of small-scale automation equipment and instruments. such as labeling machine, cutting machine. packing machine, plotter, engraving machine, CNC machine and so on.

## Electrical Specifications

Parameter	Min	Typical	Max	Unit
Input Voltage(DC)	24	-	90	VDC
Output current	0	-	6.0	A
Pulse Signal Frequency	0	-	75	KHZ
Logic Signal Current	7	10	16	MA

## 2.parameter setting

### Current setting

Switch: ON=0;OFF=1

Phase current(A)	SW1	SW2	SW3
2.00	0	0	0
2.57	1	0	0
3.14	0	1	0
3.71	1	1	0
4.28	0	0	1
4.86	1	0	1
5.43	0	1	1
6.00	1	1	1

### Standstill Current Setting

SW4 is used for standstill current setting. OFF means that the standstill current is half of the dynamic current; and ON means that standstill current is the same as the selected dynamic current. Usually the SW4 is set to OFF, in order to reduce the heat of the motor and driver.

## Micro-step Setting

Switch: ON=0;OFF=1

Micro-step	SW5	SW6	SW7	SW8
2	0	0	0	0
4	0	1	0	0
8	0	0	1	0
16	0	1	1	0
32	0	0	0	1
64	0	1	0	1
128	0	0	1	1
256	0	1	1	1
5	1	0	0	0
10	1	1	0	0
25	1	0	1	0
50	1	1	1	0
125	1	0	0	1
250	1	1	0	1

## 3.Connectors and Pin Assignment

### Control signal Connector

Control Signal connector	
Name	Description
PUL+	Pulse signal positive
PUL-	Pulse signal negative
DIR+	Direction signal positive
DIR-	Direction signal negative
ENA+	Enable signal positive, usually left unconnected(enable)
ENA-	Enable signal negative, usually left unconnected(enable)

**Power and Motor Connector**

+VDC	Power supply, +24~+90 VDC
GND	Power Ground
A+	Motor phase A
A-	
B+	Motor phase B
B-	

**Control Signal Connector Interface**




Figure1: Common-Cathode




Figure2: Common-Anode




Figure 3: Typical connection

VCC	R
5V	0
12V	680Ω
24V	1.8KΩ

Table1

## 4. Problems and Solutions

<b>problems</b>	<b>Possible cause</b>	<b>solutions</b>
<b>Motor is not rotating</b>	No power supply	Check the power supply
	No control signal	Check the control signal
	The driver is disabled	Don't connected the enable signal or enable the driver
<b>ALM lights</b>	Supply voltage is too high or too low	Check the supply voltage
	Motor line short-circuit	Check motor lines eliminate the short-circuit
	Motor line wrong connect	Check the motor wiring
	Motor or drive failure	Replace the motor or drive
<b>Motor rotates in the wrong direction</b>	Motor phases connected in reverse	Reverse the phases line
	Motor line break	Change the phases are connected
<b>Inaccurate Position</b>	The Micro steps set incorrectly.	Set the correct segments
	The motor load is too heavy.	Increasing the current
	Control signal is interfered	Eliminate interference
<b>Motor Stalled</b>	Power supply voltage too low	Increasing the supply voltage
	Accelerating time is too short.	Extend the acceleration time
	Current setting is too small	Increasing the current
	Motor torque is too small	Replace the motor

**5. Mechanical Specifications** (unit: mm(inch),1 inch = 25.4mm)

